

"G.O.SARS" streamer configuration 26.08. 2004. Svalex Isfjorden										
Sections	ASSI	Cable	Ser.No.	Bird	Weights		Date	Ch.#	Ch.#	Remarks
					Front	Aft				
		HSDJ-A								Deck cable 31m
		HSJJ								Slip-ring 0.5m
										Slip-ring adapter 3m
Lead-in		HSEJ-B								412m Leadin
Tow-Adapt.		HSRWJ	9302-009-004F				12.aug.01			REPAIR ADPT. GEL FILLED
Stretch		HSYJ-B	9611-020-001F	1-			12.aug.01			2 Bly
Front Group		HSAWJ	9109-003-001F				12.aug.01		1	
Active 1		HSSJ-B	9310-073-014F	2-		2	12.aug.01	1	8	Bird 1 (1. Seksjon tatt av)
<b>ASSI - 1</b>	<b>03-1071</b>						12.aug.01			
Active 2		HSSJ-B	9605-511-002L				12.aug.01	9	16	Bird 2
Active 3		HSSJ-B	9210-037-001F		BC	1	12.aug.01	17	24	
<b>ASSI - 2</b>	<b>03-0117</b>						12.aug.01			
Active 4		HSSJ-B	9210-289-006L	3-		3	12.aug.01	25	32	Bird 3, 1 bly
Active 5		HSSJ-B	9309-354-003L			1	12.aug.01	33	40	0 Bly
<b>ASSI - 3</b>	<b>03-1498</b>						12.aug.01			
Active 6		HSSJ-B	9503-414-006L			3	12.aug.01	41	48	1 Bly
Active 7		HSSJ-B	9203-028-014F			2	12.aug.01	49	56	1 Bly
<b>ASSI - 4</b>	<b>03-0867</b>						12.aug.01			
Active 8		HSSJ-B	9203-029-007F	4-		3	12.aug.01	57	64	Bird 4
Active 9		HSSJ-B	9510-455-055L				12.aug.01	65	72	hull - lappet
<b>ASSI - 5</b>	<b>03-1944</b>						12.aug.01			
Active 10		HSSJ-B	9507-125-009F			4	12.aug.01	73	80	0 bly
Active 11		HSSJ-B	9606-177-005F			3	12.aug.01	81	88	0 Bly
<b>ASSI - 6</b>	<b>03-1942</b>						12.aug.01			
Active 12		HSSJ-B	9304-056-001F	5-		3	12.aug.01	89	96	Bird 5, 0 bly
Active 13		HSSJ-B	9408-093-020F			2	12.aug.01	97	104	
<b>ASSI - 7</b>	<b>03-0473</b>						12.aug.01			
Active 14		HSSJ-B	9311-366-004L				12.aug.01	105	112	
Active 15		HSSJ-B	9401-374-007L			2	12.aug.01	113	120	0 Bly
<b>ASSI - 8</b>	<b>03-0039</b>						12.aug.01			
Active 16		HSSJ-B	9608-182-008F	6-		2	12.aug.01	121	128	Bird 6, 0 bly
Active 17		HSSJ-B	9506-429-003L			1	12.aug.01	129	136	0 Bly
<b>ASSI - 9</b>	<b>03-0679</b>						12.aug.01			
Active 18		HSSJ-B	9606-176-014F	a		2	12.aug.01	137	144	0 Bly
Active 19		HSSJ-B	9411-100-004F	a		2	12.aug.01	145	152	1 Bly
<b>ASSI - 10</b>	<b>03-01934</b>						12.aug.01			
Active 20		HSSJ-B	9506-427-008L	7-		2	12.aug.01	153	160	Bird 7, 0 Bly
Active 21		HSSJ-B	9508-434-009L			1	12.aug.01	161	168	1 Bly
<b>ASSI - 11</b>	<b>03-0614</b>						12.aug.01			
Active 22		HSSJ-B	9601-477-004L	a		1	12.aug.01	169	176	1 Bly
Active 23		HSSJ-B	9605-175-015F	a		1	12.aug.01	177	184	0 Bly
<b>ASSI - 12</b>	<b>03-0505</b>						12.aug.01			
Active 24		HSSJ-B	9508-444-010L	8-			12.aug.01	185	192	Bird 8
Active 25		HSSJ-B	9606-515-009L	a		1	12.aug.01	193	200	1 Bly
<b>ASSI - 13</b>	<b>03-02152</b>						12.aug.01			skiftet boble
Active 26		HSSJ-B	9301-321-006L				12.aug.01	201	208	
Active 27		HSSJ-B	9311-366-010L				12.aug.01	209	216	
<b>ASSI - 14</b>	<b>03-0863</b>						12.aug.01			
Active 28		HSSJ-B	9402-083-020F	9-		2	12.aug.01	217	224	Bird 9, 1 Bly
Active 29		HSSJ-B	9203-030-002F				12.aug.01	225	232	
<b>ASSI - 15</b>	<b>03-1826</b>						12.aug.01			
Active 30		HSSJ-B	9392-049-010F			1	12.aug.01	233	240	Bird 10, 1 Bly
<b>Power Mod.</b>			None							
Tail Stretch		HSYBJ-C	9903-007-011F	10-		0	12.aug.01			75m
TTC		TTC-C	9505-006-004F				12.aug.01			50m
Tailbouy										