

Håkon Mosby Streamer Configuration. 22.08.02

Sections	ASSI	Cable	Ser.No.	Bird		Weight		Date	Ch.#	Ch.#	Remarks
				Front		Fro	Aft	Changed			
		HSDJ-A									Deck cable 31m
		HSJJ									Slip-ring 0.5m
											Slip-ring adapter 3m
Lead-in		HSEJ-B									412m Leadin
Tow-Adapt.		HSRWJ	9302-009-004F					12.aug.01			REPAIR ADPT. GEL FILLED
Stretch		HSYJ-B	9611-020-001F	1-				12.aug.01			3 Bly
Front Group		HSAWJ	9109-003-001F					12.aug.01	1	8	
Active 1		HSSJ-B	9310-073-014F	2-		2		12.aug.01	1	8	Bird 1
ASSI - 1	03-1071							12.aug.01			
Active 2		HSSJ-B	9611-189-008F					12.aug.01	9	16	Bird 2
Active 3		HSSJ-B	9210-037-001F		BC	1		12.aug.01	17	24	
ASSI - 2	03-0117							12.aug.01			
Active 4		HSSJ-B	9210-289-006L	3-		3		12.aug.01	25	32	Bird 3, 2 bly
Active 5		HSSJ-B	9309-354-003L			1		12.aug.01	33	40	1 Bly
ASSI - 3	03-1414							12.aug.01			
Active 6		HSSJ-B	9503-414-006L			3		12.aug.01	41	48	1 Bly
Active 7		HSSJ-B	9203-028-014F			2		12.aug.01	49	56	1 Bly
ASSI - 4	03-0867							12.aug.01			
Active 8		HSSJ-B	9203-029-007F	4-		3		12.aug.01	57	64	Bird 4
Active 9		HSSJ-B	9510-455-055L					12.aug.01	65	72	
ASSI - 5	03-1944							12.aug.01			
Active 10		HSSJ-B	9507-125-009F			4		12.aug.01	73	80	
Active 11		HSSJ-B	9606-177-005F			3		12.aug.01	81	88	1 Bly
ASSI - 6	03-1942							12.aug.01			
Active 12		HSSJ-B	9304-056-001F	5-		3		12.aug.01	89	96	Bird 5, 2 bly
Active 13		HSSJ-B	9408-093-020F			2		12.aug.01	97	104	
ASSI - 7	03-0473							12.aug.01			
Active 14		HSSJ-B	9311-366-004L					12.aug.01	105	112	
Active 15		HSSJ-B	9401-374-007L			2	0	12.aug.01	113	120	2 Bly
ASSI - 8	03-0039							12.aug.01			
Active 16		HSSJ-B	9608-182-008F	6-		2		12.aug.01	121	128	Bird 6, 2 bly
Active 17		HSSJ-B	9506-429-003L			1		12.aug.01	129	136	1 Bly
ASSI - 9	03-0679							12.aug.01			
Active 18		HSSJ-B	9606-176-014F		a	2		12.aug.01	137	144	2 Bly
Active 19		HSSJ-B	9411-100-004F		a	2		12.aug.01	145	152	2 Bly
ASSI - 10	03-01934							12.aug.01			
Active 20		HSSJ-B	9506-427-008L	7-		2		12.aug.01	153	160	2 Bly
Active 21		HSSJ-B	9508-434-009L			1		12.aug.01	161	168	Bird 7, 1 Bly
ASSI - 11	03-0614							12.aug.01			
Active 22		HSSJ-B	9601-477-004L		a	1		12.aug.01	169	176	1 Bly
Active 23		HSSJ-B	9605-175-015F		a	1		12.aug.01	177	184	1 Bly
ASSI - 12	03-0505							12.aug.01			
Active 24		HSSJ-B	9508-444-010L	8-				12.aug.01	185	192	Bird 8
Active 25		HSSJ-B	9606-515-009L		a	1		12.aug.01	193	200	1 Bly
ASSI - 13	03-02152							12.aug.01			
Active 26		HSSJ-B	9301-321-006L					12.aug.01	201	208	
Active 27		HSSJ-B	9311-366-010L					12.aug.01	209	216	
ASSI - 14	03-0863							12.aug.01			
Active 28		HSSJ-B	9402-083-020F	9-		2		12.aug.01	217	224	Bird 9, 2 Bly
Active 29		HSSJ-B	9203-030-002F					12.aug.01	225	232	
ASSI - 15	03-1826							12.aug.01			
Active 30		HSSJ-B	9392-049-010F			1		12.aug.01	233	240	Bird 10, 1 Bly
Power Mod.			None								
Tail Stretch		HSYBJ-C	9903-007-011F	10-		0	0	12.aug.01			75m
TTC		TTC-C	9505-006-004F					12.aug.01			50m
Tailbouy											