



A-G Geophysical Products, Inc.  
(281) 373-5952 fax (281) 373-3632

## IMPORTANT INFORMATION

### Underwater Electrical Connectors MATING

#### BEFORE SHIPMENT

A-G connectors are lightly sprayed with an AEROSOL non-water-soluble silicon lubricant, in preparation for the first connection.

#### FOR SUBSEQUENT MATINGS

the connectors should be cleaned to remove any contamination and silicon buildup, then re-lubricated. This procedure will insure correct mating as well as prolonged connector life.

If there is any EXCESS lubricant within the sealing cavity, the connectors WILL NOT MATE.

Only use SILICON SPRAY approved for POLYURETHANE application.

DO NOT use WD40, CRC, or any other organic-based solvent spray.



DO NOT use DC 111 or any other heavy silicon greases.


### Mating of Locking Rings should be done BY HAND only.

USE OF A WRENCH OR PLIERS can cause thread damage and can lead to failure of the locking rings.

**X** DO NOT BEND or TWIST.



**✓** Pull STRAIGHT across connectors, or anchor with foot and pull STRAIGHT up.



#### FOR TROUBLE-FREE SERVICE

use a light machine oil or anti-seize DIELECTRIC product to lubricate **ONLY** the **THREADED** portion of the stainless steel locking rings.

PULLING APART

